
3/8" CORDLESS DRILL 12V

Model 6216D
Model 6216DWBE



WIRING DIAGRAM

IMPORTANT! - To assure product SAFETY and RELIABILITY, repairs, maintenance or adjustments should be performed by MAKITA Service Centers, or other qualified service organizations. Always use MAKITA replacement parts.

Fig.	Part No.	Qty. Used	Description
2	266130-9	7	T. SCREW BIND PT3x16
3	911143-2	1	P.H. SCREW M4x22
4	344391-2	2	BIT HOLDER
5	183079-7	1	HOUSING Set (Incl. Fig. 19)
6	125091-1	1	SPEED CHANGE LEVER Ass'y (Incl. 2ea. 231433-0 Conpression Spring 4)
7	416079-5	1	F/R CHANGE LEVER
8	651939-6	1	SWITCH
9	687085-9	1	HOLDER
10	654168-0	1	SPRING TERMINAL (+)
11	654169-8	1	SPRING TERMINAL (-)
12	251464-3	1	F.H. SCREW M6x22
14	125088-0	1	GEAR Ass'y
15	629733-4	1	DC MOTOR 12V (Incl. 1ea. 226361-2 Spur Gear 20 & 191971-3 Carbon Brush CB-430 Set; 2ea. 643929-3 Holder Cap)
16	265999-8	4	TAPPING SCREW 4x25
17	266134-1	3	TAPPING SCREW ST 4x8
18	911006-2	1	P.H. SCREW M3x8
19	183079-7	1	HOUSING Set (Incl. Fig. 5)
20	343579-1	1	SET PLATE
21	122575-0	1	GRIP Ass'y

ACCESSORIES

400	763144-4	1	KEYLESS DRILL CHUCK 10
401	122576-8	1	STOPPER POLE
402	784614-0	2	PLILLIPS/SLOTTED BIT 2-45
403	414938-7	2	BATTERY COVER
404	192698-A	2	NI-MH (2.2A) BATTERY 1233
405	DC1411	1	FAST CHARGER
406	824525-8	1	PLASTIC TOOL CASE