
JET DC-1200A-3 | Stock 708635

Diagram A - Dust Collector - Shared Phase Reference

Dust Collector | Original JET parts reference



mmToolParts
Big Time Experience. Small Town Service. .com

JET DC-1200A-3 | Stock 708635

Parts List A - Dust Collector - Shared Phase Reference

Dust Collector | Original JET parts reference

Ref.	Part number	Description	Size	Qty.
1	411035W	Impeller Housing		1
2	411026W	Motor Bracket		1
3	998621	Strain Relief		1
4	MA411003	Motor	2 HP, 1Ph	1
	MA411003-3	Motor	2 HP, 3 Ph	1
	DC1100-50W	Motor Fan Cover (not shown)		1
	MF411012	Motor Fan (not shown)		1
	CA003030	Running Capacitor (not shown)	30MFD, 300V	1
	CA020010	Starting Capacitor (not shown)	200MFD, 125V	1
5	411051	Switch Box		1
6	411053	Switch Plate		1
7	994542	Switch	1 Ph	1
	DC1900-23B	Switch	3 Ph	1
8	IC420002	Power Cord		1
9	420051	Motor Packing		1
10	AB411059	Impeller	12”	1
11	411036W	Inlet Guard		1
12	427028	Inlet Port	2 @ 4”	1
13	420203	Inlet Cap		2
14	430034	Inlet Flange Packing		1
15	411041W	Base		1
16	402036	Pivoting Caster		4
17	420012W	Housing		1
18	402004W	Support		3
19	523011W	Hanger Bracket		1
20	411009	Hose	5”x65(CM)	1
21	420010	Ring Clamp	5”	2
22	402040	Hanger	30 Micron Bag Hanger	1
	AB430039	Hanger	5 Micron Bag Hanger	1
24	708698	Filter Bag	30 Micron Bag	1
	708702	Filter Bag	5 Micon Bag	1
25	AB410012	Retainer Strap		1

Blank references and quantities match the JET manual. JET shared list retains both single- and three-phase alternatives; select parts for the named stock.

mmToolParts
Big Time Experience. Small Town Service. .com

JET DC-1200A-3 | Stock 708635

Parts List A - Dust Collector - Shared Phase Reference (continued)

Dust Collector | Original JET parts reference

Ref.	Part number	Description	Size	Qty.
26	708699A	Collection Bag		1
27	450038	Bracket Cap		1
31	ST039304	Tapping Screw	M3.5x12(AB)	6
32	KS050525	Key	5x5x25	1
34	TS-1540061	Nut	M8	10
35	TS-0561031	Nut	3/8”-16UNC	4
36	SH080402	Hex Head Bolt	M8x20 L.H	1
37	TS-1490011	Hex Head Bolt	M8x12	4
38	TS-1490021	Hex Head Bolt	M8x16	16
39	TS-1490041	Hex Head Bolt	M8x25	4
40	TS-1554041	Pan Head Bolt W/Flange	M6x12	2
41	TS-0680031	Flat Washer	M8	1
42	TS-1554041	Pan Head Bolt W/Flange	M6x12	8
43	TS-0680031	Flat Washer	M8	34
44	TS-0720081	Spring Washer	M8	8
45	TS-1551071	Spring Washer	M10	4
46	ST059304	Tapping Screw	M5x12	2
	DC1200-53	Grounding Label (not shown)		1
	DC1200-54	Direction Label (not shown)		1
	DC1200A-NP	Name Plate (not shown)		1
	DC1100-HP	Hardware Package (not shown)		1
	DC1200A-CS	Centrifugal Switch (not shown)		1
	DC1900-53	Warning Label (not shown)		1


Blank references and quantities match the JET manual. JET shared list retains both single- and three-phase alternatives; select parts for the named stock.

mmToolParts
Big Time Experience. Small Town Service. .com

JET DC-1200A-3 | Stock 708635

Diagram B - 230V / 460V Three-phase Wiring

Dust Collector | Original JET parts reference



mmToolParts
Big Time Experience. Small Town Service. .com