
JET DC-1200FS | Stock 708629

Diagram A - Floor-sweep Dust Collector

Dust Collector | Original JET parts reference



mmToolParts
Big Time Experience. Small Town Service. .com

JET DC-1200FS | Stock 708629

Parts List A - Floor-sweep Dust Collector

Dust Collector | Original JET parts reference

Ref.	Part number	Description	Size	Qty.
1	427001	Upper Housing		1
2	427074	Pad		2
3	427002	Impellar Guard		1
4	427058	Extension Guard		1
5	427003	Gasket		1
6	427004	Lower Housing		1
7	427057	Locating Pieces		2
8	427005	Housing Edge Sleeve		1
9	427415AS	Motor	1 1/2HP, 1Ph	1
	4272115-2	Motor Fan Cover (not shown)		1
	4272115-1	Motor Fan (not shown)		1
	991016	Running Capacitor (not shown)		1
	991400	Starting Capacitor (not shown)		1
	991401	Capacitor Cover (not shown)		1
10	994532	Switch		1
11	999910	Power Cord		1
12	423023	Motor Seal		1
13	427009	Motor Flange		1
14	430034	Flange Gasket		1
15	AB430006	Impeller	12”	1
16	427018	Base		1
17	427017	Base Guard		1
18	427019	Fixed Caster		2
19	427020	Pivoting Caster		2
20	427015	Lower Stand		1
21	427033	Air Guard		1
22	427971	Pad		1
23	427028	Inlet		1
24	420203	Inlet Guard		1
25	427027	O-ring		1
26	427016	Base Gasket		1
27	427013	Upper Stand		1

Blank references and quantities match the JET manual.

mmToolParts
Big Time Experience. Small Town Service. .com

JET DC-1200FS | Stock 708629

Parts List A - Floor-sweep Dust Collector (continued)

Dust Collector | Original JET parts reference

Ref.	Part number	Description	Size	Qty.
28	427014	O-ring		1
29	427012	Housing Gasket		1
30	427021	Support Tubing		2
31	427031	Handle		1
32	427056	Plug	7/8”	2
33	427023	Hanger		1
34	709561	Filter Bag		1
35	427024	Retainer Strap		2
36	709560	Collection Bags		10
41	KS070720	Key	7x7x20	1
42	TS-1540041	Nut	M6	21
43	NH081300	Nut	M8	2
44	TS-0561031	Nut	3/8”-16UNC	2
45	TS-059303	Acorn Nut	3/8”-16UNC	2
46	TS-0561072	Nut	5/8”-18UNF	1
47	TS-1482021	Cap Screw	M6x12	8
48	SH069400	Hex Head Bolt	M6x16	8
49	TS-1482041	Cap Screw	M6x20	10
50	TS-1482101	Cap Screw	M6x50	4
51	TS-1490021	Cap Screw	M8x16	6
52	TS-1490031	Cap Screw	M8x20	8
53	SF069300	Pan Head Flange Bolt	M6x12	14
54	SR069200	Hex Socket Cap Bolt	M6x8	2
55	ST039304	Tapping Screw	M3.5x12	11
56	ST040200	Tapping Screw	M4x10	28
57	TS-1550041	Flat Washer	M6	13
58	TS-1550061	Flat Washer	M8	6
59	TS-1550071	Flat Washer	M10	2
60	WF164030	Flat Washer	M16	1
61	TS-1551041	Spring Washer	M6	33
62	TS-1551061	Spring Washer	M8	14
63	TS-1551071	Spring Washer	M10	2


Blank references and quantities match the JET manual.

mmToolParts
Big Time Experience. Small Town Service. .com

JET DC-1200FS | Stock 708629

Diagram B - Motor Connections

Dust Collector | Original JET parts reference




mmToolParts
Big Time Experience. Small Town Service. .com

JET DC-1200FS | Stock 708629

Diagram C - 115V / 230V Wiring

Dust Collector | Original JET parts reference



mmToolParts
Big Time Experience. Small Town Service. .com