
JET DC-1900A-3 | Stock 708638

Diagram A - Collector Assembly

Dust Collector | Original JET parts reference



mmToolParts
Big Time Experience. Small Town Service. .com

JET DC-1900A-3 | Stock 708638

Parts List A - Collector Assembly

Dust Collector | Original JET parts reference

Ref.	Part number	Description	Size	Qty.
1	431018W	Impeller Housing		1
2	431019W	Impeller Housing Bracket		1
3	431020W	Motor Bracket		1
4	450038	Bracket Cap		1
5	DC1900-20W	Motor	3HP, 1Ph 230V Only	1
	431024-3PHW	Motor……	3HP, 3Ph 230/460V prewired 230V	1
	DC1900-MFC	Motor Fan Cover (not shown)		1
	DC1900-MF	Motor Fan (not shown)		1
	DC1900-20B	Starting Capacitor (not shown)	600MFD, 125VAC	1
	DC1900-CS	Centrifugal Switch and Rotor (not shown)		1
6	IM431001	Motor Cord		1
7	994542	Switch	1 Ph	1
	DC1900-23B	Switch	3 Ph	1
8	DC1900-33	Power Cord		1
9	420051	Motor Gasket		1
10	431006	Impeller	14”	1
11	431008W	Inlet Guard	8”	1
12	431025	Inlet Port	(3) 4”	1
13	420203	Inlet Cap		2
14	431034	Rubber Gasket		1
15	430028W	Base		1
16	402036	Pivoting Caster		4
17	430004W	Connector Tube		1
18	430035	Rubber Gasket		1
19	430036	Rubber Gasket		2
20	430012W	Left Housing		1
21	430020W	Right Housing		1
22	402004W	Support Bar		2
23	523011W	Hanger Bracket		2
24	430039	Upper Hanger……	used w/30 micron filter bag	2
	430038	Upper Hanger……used w/5 micron filter bag		2

Blank references and quantities match the JET manual. JET M-708637 Rev G, 02/2004. Three-phase 230V / 460V stock. Shared parts list retains both motor alternatives; select the motor matching the machine nameplate.

mmToolParts
Big Time Experience. Small Town Service. .com

JET DC-1900A-3 | Stock 708638

Parts List A - Collector Assembly (continued)

Dust Collector | Original JET parts reference

Ref.	Part number	Description	Size	Qty.
25	430037	Support Bar		2
26	708689	Filter Bag	30 micron	2
	708703	Filter Bag	5 micron	2
27	430005	Retainer Strap		2
28	708699A	Collection Bag		2
29	998654	Strain Relief		2
30	990855	Pan Head Bolt w/Flange	3/16 x 1/2”	1
31	992021	Key	7x7x20	1
32	TS-0560071	Hex Nut	#10 –24	1
33	TS-1540061	Hex Nut	M8	30
34	TS-0561031	Hex Nut	3/8” –16 UNC	4
35	TS-0561072	Hex Nut	5/8” –18 UNF	1
36	TS-1490011	Hex Cap Screw	M8x12	10
37	TS-1490031	Hex Cap Screw	M8x20	36
38	TS-1490041	Hex Cap Screw	M8x25	4
39	TS-081C032	Machine Screw	#10–24 x 1/2"	1
40	TS-081C062	Machine Screw	#10–24 x 1"	2
41	TS-1554041	Pan Head Bolt W/Flange	M6x12	10
42	TS-1550061	Flat Washer	M8	64
43	TS-1550071	Flat Washer	M10	6
44	TS-155010	Flat Washer	M16	1
45	TS-2361081	Lock Washer	M8	14
46	TS-2361101	Lock Washer	M10	4
47	WE050000	Star Washer (Ext)	M5	4
48	430029W	Extension Plate		2
49	TS-1490031	Hex Cap Screw	M8x20	4
50	TS-1550061	Flat Washer	M8	4
51	TS-2361081	Lock Washer	M8	4
52	TS-1540061	Hex Nut	M8	4
	DC1900-30	Grounding Label (not shown)		1
	DC1900-31	Direction Label (not shown)		1
	DC1900-1/3-ID	Identification Label (not shown)		1

Blank references and quantities match the JET manual. JET M-708637 Rev G, 02/2004. Three-phase 230V / 460V stock. Shared parts list retains both motor alternatives; select the motor matching the machine nameplate.

mmToolParts
Big Time Experience. Small Town Service. .com

JET DC-1900A-3 | Stock 708638

Parts List A - Collector Assembly (continued)

Dust Collector | Original JET parts reference

Ref.	Part number	Description	Size	Qty.
	DC1900-32	Name Plate (not shown)		1
	DC1900-HP	Hardware Package (not shown)		1
	DC1900-53	Warning Label (Base - not shown)		1
	DC1900-54	Warning Label (Inlet Guard - not shown)		1


Blank references and quantities match the JET manual. JET M-708637 Rev G, 02/2004. Three-phase 230V / 460V stock. Shared parts list retains both motor alternatives; select the motor matching the machine nameplate.


mmToolParts
Big Time Experience. Small Town Service. .com

JET DC-1900A-3 | Stock 708638

Diagram B - Three-phase 230V / 460V Wiring

Dust Collector | Original JET parts reference





mmToolParts
Big Time Experience. Small Town Service. .com