
DCD1007WW1 Type 1 - Parts List

Use the figure number to match each part to the corresponding parts schematic.


DeWalt ServiceNet: DCD1007WW1 Type 1 | Additional parts have no assigned figure



NOTES:

1. TORQUE TO 18.0-19.0 Nm (159.3-168.2 IN-LBS .)
2. TORQUE TO 1.2-1.6 Nm (10-14 IN-LBS .) HOUSINGS TO BE HELD FIRMLY TOGETHER WHEN DRIVING THESE SCREWS. TH ESE SCREWS TO BE DRIVEN BEFORE HOUSING SCR EWS.
3. TORQUE TO 0.6-0.8 Nm (5-7 IN-LB S.)
4. TORQUE TO 0.3 ±0.1 Nm (2 .7 ±0.9 IN-LBS.)
5. TORQUE TO 0.9-1.13 Nm (8-10 IN-LBS .)
6. TORQUE TO 1.85-2.09 Nm (16 .4-18.5 IN-LBS .)
7. TORQUE TO 1.13-1.35 Nm (10-11.95 IN-LBS.).

REFER TO PARTS LIST



mmToolParts
Big Time Experience. Small Town Service. .com

DCD1007WW1 Type 1 - Parts List

Use the figure number to match each part to the corresponding parts schematic.

DeWalt ServiceNet: DCD1007WW1 Type 1 | Additional parts have no assigned figure

Fig. 1	NA568824	SCREW
Fig. 2	N568902	WASHER
Fig. 3	N765979	CHUCK
Fig. 4	NA412325	END CAP
Fig. 5	NA127592	SCREW
Fig. 6	NA612313	SPINDLE SA
Fig. 7	N165352	DETENT
Fig. 8	NA117275	CLUTCH
Fig. 9	NA068412	SPRING
Fig. 10	NA151270	PIN
Fig. 11	NA473520	SPRING
Fig. 12	NA485646	RATCHET
Fig. 13	NA378595	SPRING
Fig. 14	NA033307	CAM
Fig. 15	NA029259	PCB
Fig. 16	330019-52	SCREW
Fig. 17	330041-37	PIN
Fig. 18	NA166102	GEARCASE
Fig. 18	NA734406	GEARCASE
Fig. 19	NA418764	BEARING BALL
Fig. 20	N118088	SCREW
Fig. 21	NA381271	WASHER
Fig. 22	NA380722	LOCKING RING
Fig. 23	NA425678	ANVIL
Fig. 24	N862801	O RING
Fig. 25	NA380705	PIN
Fig. 26	N866170	GEAR
Fig. 27	NA612307	GEAR
Fig. 28	NA612298	GEAR SA

mmToolParts
Big Time Experience. Small Town Service. .com

DCD1007WW1 Type 1 - Parts List

Use the figure number to match each part to the corresponding parts schematic.

DeWalt ServiceNet: DCD1007WW1 Type 1 | Additional parts have no assigned figure

Fig. 29	NA612290	SWITCH SA
Fig. 30	NA202421	COVER
Fig. 31	N281559	SCREW
Fig. 32	NA741291	SWITCH & LEAD SA
Fig. 33	NA612260	MOTOR & SWITCH SA
Fig. 34	682211-00	SCREW
Fig. 35	330019-39	SCREW
Fig. 37	N787996	INSERT
Fig. 38	N831593	SCREW
Fig. 39	N929081	SPRING COMPRESSION
Fig. 40	NA263935	RETAINER
Fig. 41	N071836	ROLL PIN
Fig. 42	N431555	ACTUATOR FWD/REV
Fig. 43	N014681	LEAF SPRING
Fig. 44	N828129	HOUSING SA
Fig. 45	N779489	HANDLE SIDE SA
Fig. 50	NA611679	TRANSMISSION SA
Fig. 51	N859056	HOOK SA
Fig. 52	NA612251	CHUCK SA
Fig. 53	NA186385	LABEL
Fig. 54	NA186386	LABEL
Fig. 55	NA184786	RATING LABEL
Fig. 56	NA534924	LABEL
Fig. 57	NA334299	LABEL
Fig. 60	N042665	SCREW
Fig. 61	N086039	HOOK
Fig. 70	NA724795	GASKET
Fig. 800	N017298	GREASE
Fig. 862	NA705139	BAG SA

mmToolParts
Big Time Experience. Small Town Service. .com

DCD1007WW1 Type 1 - Parts List

Use the figure number to match each part to the corresponding parts schematic.
DeWalt ServiceNet: DCD1007WW1 Type 1 | Additional parts have no assigned figure

Fig. 866	DCB2108	BATTERY
Fig. 871	DCB118	CHARGER

mmToolParts
Big Time Experience. Small Town Service. .com