

DCG418SHDX2 Type 1 - Parts List

Use the figure number to match each part to the corresponding parts schematic.

NOTES:

1. TORQUE TO 9-11 Nm (80-97 IN-LBS).
2. TORQUE TO 1.2-1.6 Nm (10.6-14.2 IN-LBS).
3. TORQUE TO 1.2-1.4 Nm (10.6-12.4 IN-LBS).
4. TORQUE TO 2.2-2.4 Nm (19.5-21.2 IN-LBS).
5. TORQUE TO 0.45-0.65Nm (4-5.8 IN-LBS).
6. GEAR TEETH ARE TO BE COATED WITH GREASE GREASE REQUIREM ENT: 15-17g.





mmToolParts
Big Time Experience. Small Town Service. .com

DCG418SHDX2 Type 1 - Parts List

Use the figure number to match each part to the corresponding parts schematic.

Fig. 1	NA533117	GEARCASE SA
Fig. 2	N263579	SPRING
Fig. 3	N481683	LOCK PIN
Fig. 4	N263699	O RING
Fig. 5	NA533122	SWITCH SA
Fig. 6	N278899	BUTTON
Fig. 7	N175104	BEARING
Fig. 8	N119639	O RING
Fig. 10	N461411	PINION
Fig. 11	N372039	NUT
Fig. 12	N508183	GEARCASE COVER SA
Fig. 13	N637725	LEVER
Fig. 14	N297219	SCREW
Fig. 15	330045-06	SCREW
Fig. 16	N465886	SPRING
Fig. 17	NA074009	HOUSING SA
Fig. 18	N436965	VENT
Fig. 19	N575500	SCREW
Fig. 20	N412210	SCREW
Fig. 21	330019-04	SCREW
Fig. 23	N115381	INNER FLANGE
Fig. 24	N484249	OUTER FLANGE
Fig. 27	NA533140	ARMATURE SA
Fig. 28	330015-00	NUT
Fig. 29	N071836	ROLL PIN
Fig. 30	N467560	PLATE
Fig. 32	N487793	GUARD
Fig. 33	NA356596	GUARD
Fig. 34	N461735	SPRING

mmToolParts
Big Time Experience. Small Town Service. .com

DCG418SHDX2 Type 1 - Parts List

Use the figure number to match each part to the corresponding parts schematic.

Fig. 35	N091479	MOUNT
Fig. 39	NA533143	MOTOR & SWITCH SA
Fig. 40	330045-01	SCREW
Fig. 41	NA596176	GUARD
Fig. 42	NA066293	WASHER
Fig. 700	NA354238	RATING LABEL
Fig. 701	000000-11	NO LONGER REQUIRED ON THIS UNIT
Fig. 701	NA354237	WARNING LABEL
Fig. 800	583534-00	GREASE
Fig. 801	N107295	HEX KEY
Fig. 836	5140229-19	SERVICE TOOL
Fig. 845	DCG418SH	HANDLE SA
Fig. 856	N302482	WHEEL GRINDING
Fig. 862	NA705142	BAG
Fig. 866	DCB609	BATTERY
Fig. 871	DCB118	CHARGER

mmToolParts
Big Time Experience. Small Town Service. .com