
DCS383H1 Type 1 - Parts List

Use the figure number to match each part to the corresponding parts schematic.
DeWalt ServiceNet: DCS383H1 Type 1 | Additional parts have no assigned figure



NOTES:

1. TORQUE TO 1.7-2.1 Nm.
2. TORQUE TO 3.4-4.5 Nm.
3. TORQUE TO 1.1-1.7 Nm.
4. TORQUE TO 0.8-1.0 Nm.
5. TORQUE TO 4.0-4.5 Nm.
6. TORQUE TO 4.0-4.8 Nm.
7. TORQUE TO 0.9-1.1 Nm.
8. TORQUE TO 2.0-2.2 Nm.
9. TORQUE TO 6.2-6.8 Nm.
10. TORQUE TO 2.3-2.8 Nm.
11. TORQUE TO 10.0-15.0 Nm.
12. GEAR TEETH ARE TO BE CODED WITH GREASE REQUIREMENT: 9-11g.

mmToolParts
Big Time Experience. Small Town Service. .com

DCS383H1 Type 1 - Parts List

Use the figure number to match each part to the corresponding parts schematic.
DeWalt ServiceNet: DCS383H1 Type 1 | Additional parts have no assigned figure

Fig. 1	NA638025	GEARCASE SA
Fig. 3	NA165152	LIMITER
Fig. 4	N514767	SCREW
Fig. 5	NA334827	WINDOW
Fig. 6	NA295246	PLATE
Fig. 8	N380571	O-RING
Fig. 9	NA201075	SEAL
Fig. 11	NA261889	CLAMSHELL
Fig. 12	NA261890	COLLECTOR
Fig. 13	NA277859	COVERPLATE
Fig. 14	NA352707	SPRING
Fig. 15	NA266447	BUTTON
Fig. 17	NA421712	HOUSING HANDLE
Fig. 19	NA407615	BAFFLE
Fig. 20	330019-05	SCREW
Fig. 21	NA638641	MOTOR & SWITCH SA
Fig. 22	NA411963	END CAP
Fig. 23	NA421703	SHOE SA
Fig. 24	NA133400	PIN
Fig. 25	NA143683	HANDLE
Fig. 26	N422878	BUTTON LOCK-OFF
Fig. 27	N433343	SPRING
Fig. 28	330019-10	SCREW
Fig. 29	N420180	SPANNER
Fig. 30	N091479	MOUNT
Fig. 31	N461735	SPRING
Fig. 32	330019-03	SCREW
Fig. 33	NA315291	LED LIGHT
Fig. 34	330045-49	SCREW

mmToolParts
Big Time Experience. Small Town Service. .com

DCS383H1 Type 1 - Parts List

Use the figure number to match each part to the corresponding parts schematic.
DeWalt ServiceNet: DCS383H1 Type 1 | Additional parts have no assigned figure

Fig. 35	NA410409	GUARD LOWER
Fig. 36	N100123	SPRING
Fig. 37	385915-04	SCREW
Fig. 38	N090570	LEVER LOCK
Fig. 39	330065-25	SCREW
Fig. 40	NA357953	PAD
Fig. 41	NA277861	GUARD
Fig. 42	330045-45	SCREW
Fig. 43	NA322871	LEVER
Fig. 44	NA296408	BUSHING
Fig. 45	NA352622	SPRING
Fig. 46	381066-00	BUMPER
Fig. 47	N086135	SCREW
Fig. 49	NA410410	GEARCASE COVER
Fig. 50	NA638024	SPINDLE SA
Fig. 51	N796738	SCREW
Fig. 52	NA252752	HUB
Fig. 53	N503419	SCREW
Fig. 54	NA415942	CARRIAGE BOLT
Fig. 55	330045-14	SCREW
Fig. 56	N419350	LEVER
Fig. 57	NA412111	THREADED ROD
Fig. 58	NA398628	WASHER
Fig. 59	330045-19	SCREW
Fig. 60	NA638017	GEAR SA
Fig. 61	NA246667	SPRING TORSION
Fig. 62	NA206066	WASHER
Fig. 63	N084137	WASHER INNER CLAMP
Fig. 64	145343-01	WASHER OUTER CLAMP

mmToolParts
Big Time Experience. Small Town Service. .com

DCS383H1 Type 1 - Parts List

Use the figure number to match each part to the corresponding parts schematic.
DeWalt ServiceNet: DCS383H1 Type 1 | Additional parts have no assigned figure

Fig. 65	145344-00	SCREW
Fig. 66	N120426	RETAINER
Fig. 67	NA252290	SPRING
Fig. 69	NA596767	HOLDER
Fig. 70	NA638638	ROTOR SA
Fig. 72	NA664119	SEAL
Fig. 800	583534-00	GREASE
Fig. 866	DCBP520	BATTERY
Fig. 871	DCB1106YY	CHARGER

mmToolParts
Big Time Experience. Small Town Service. .com