
DW221-CA Type 1 - Parts List

Use the figure number to match each part to the corresponding parts schematic.

DeWalt ServiceNet: DW221-CA Type 1 | Additional parts have no assigned figure



mmToolParts
Big Time Experience. Small Town Service. .com

DW221-CA Type 1 - Parts List

Use the figure number to match each part to the corresponding parts schematic.
DeWalt ServiceNet: DW221-CA Type 1 | Additional parts have no assigned figure

Fig. 1	176853-00SV	ARMATURE & FAN
Fig. 2	176849-00SV	FIELD
Fig. 3	176846-04	BRUSH
Fig. 5	N440281	BRUSH HOLDER,L
Fig. 6	N440280	BRUSH HOLDER,R
Fig. 7	5140102-21	SWITCH KIT
Fig. 8	330072-98	CORDSET
Fig. 10	330003-04	BEARING
Fig. 11	449192-00	TERMINAL
Fig. 13	429969-03	FIELDCASE
Fig. 14	610140-01	HANDLE COVER
Fig. 15	176829-00	CORD CLAMP
Fig. 16	330005-01	CORD PROTECTOR
Fig. 17	330019-13	SCREW
Fig. 18	176951-00	SCREW
Fig. 19	949721-03	SLEEVE
Fig. 20	176811-00	BAFFLE
Fig. 21	949638-02	DAMPER
Fig. 22	395047-00	BRAND LABEL
Fig. 23	176742-00	NAMEPLATE
Fig. 24	176715-00	CASE,GR
Fig. 25	176688-00	SPINDLE,OUTPUT
Fig. 26	605040-20	BEARING
Fig. 27	176691-01	SPACER
Fig. 28	388761-00	GEARCASE COVER
Fig. 29	023813-00	WASHER FIBRE
Fig. 30	176682-00	GEAR SA
Fig. 32	605256-01	SCREW
Fig. 33	176640-00	CAP

mmToolParts
Big Time Experience. Small Town Service. .com

DW221-CA Type 1 - Parts List

Use the figure number to match each part to the corresponding parts schematic.
DeWalt ServiceNet: DW221-CA Type 1 | Additional parts have no assigned figure

Fig. 34	287982-00	CHUCK & KEY
Fig. 43	136086-02	TERMINAL
Fig. 45	330019-14	SCREW
Fig. 46	176655-00	GASKET
Fig. 48	087692-00	RETAINER
Fig. 50	093128-00	BEARING NEEDLE
Fig. 54	330004-00	BEARING
Fig. 55	176731-00SV	SPINDLE & GEAR
Fig. 56	091817-00	WASHER
Fig. 57	091644-00	BEARING THRUST
Fig. 58	330019-16	SCREW
Fig. 80	330034-02	CHUCK KEY
Fig. 81	065288-02	HOLDER
Fig. 800	286436-00	GREASE
Fig. 856	176929-00	CLIP,LOCK-OUT

mmToolParts
Big Time Experience. Small Town Service. .com

DW221-CA Type 1 - Parts List

Use the figure number to match each part to the corresponding parts schematic.

DeWalt ServiceNet: DW221-CA Type 1 | Additional parts have no assigned figure

Additional parts - no figure assigned by DeWalt

-	148204-00	SCREW
-	149474-00	BRAND LABEL
-	176731-00	SPINDLE & GEAR
-	176800-02	BRUSH HOLDER
-	176801-02	BRUSH HOLDER
-	176815-03	CASE,FIELD
-	176830-43	SWITCH
-	176846-02	BRUSH 120V
-	176849-00	FIELD
-	176853-00	ARMATURE & FAN
-	176899-00	COVER,HANDLE
-	176950-00	BEARING
-	23813-00	WASHER
-	330003-09	BEARING
-	65288-02	HOLDER
-	87692-00	RETAINER
-	91644-00	BEARING
-	91817-00	WASHER THRUST
-	93128-00	BEARING NEEDLE
-	93129-00	BEARING NEEDLE

mmToolParts
Big Time Experience. Small Town Service. .com