
DW821-CA Type 3 - Parts List

Use the figure number to match each part to the corresponding parts schematic.



mmToolParts
Big Time Experience. Small Town Service. .com

DW821-CA Type 3 - Parts List

Use the figure number to match each part to the corresponding parts schematic.

Fig. 101	401702-07	ARMATURE 115V
Fig. 102	395991-01	FIELD 115V
Fig. 103	945614-00	SWITCH
Fig. 104	939539-00	BRUSH CUT OFF
Fig. 105	330072-47	POWER CORD
Fig. 106	401678-06	WASHER
Fig. 107	389181-00	FLANGE,INNER
Fig. 108	562160-06	SCREW
Fig. 109	605415-00	RETAINING PLATE
Fig. 110	390020-00	GUARD
Fig. 111	393576-00	RING
Fig. 112	562160-07	SCREW
Fig. 113	945298-00	GEARCASE COVER
Fig. 114	391473-00	SPINDLE
Fig. 116	330005-01	CORD PROTECTOR
Fig. 117	390701-00	GEAR
Fig. 118	562097-01	SCREW
Fig. 119	610704-01	SERVICE KIT
Fig. 121	N239381	SIDE HANDLE
Fig. 122	945299-00	FLANGE
Fig. 123	945292-00	NUT
Fig. 124	944574-00	BUTTON
Fig. 125	562210-00	SPRING
Fig. 126	944571-00	SPINDLE LOCK
Fig. 127	605040-22	BEARING
Fig. 128	930275-00	SLEEVE
Fig. 129	401623-00	BAFFLE
Fig. 130	949638-01	BUFFER
Fig. 132	395985-00S	BRUSH HOLDER

mmToolParts
Big Time Experience. Small Town Service. .com

DW821-CA Type 3 - Parts List

Use the figure number to match each part to the corresponding parts schematic.

Fig. 133	562204-00	SPRING
Fig. 134	609938-00	FIELD CASE KIT
Fig. 135	605040-02	BEARING
Fig. 136	613186-00	END CAP
Fig. 137	5140000-13	SWITCH SUPPORT
Fig. 138	401680-00	WRENCH
Fig. 139	562097-05	SCREW
Fig. 140	401622-01	FLANGE
Fig. 145	562097-00	SCREW
Fig. 149	402489-00	PAD
Fig. 153	562100-01	PINION
Fig. 160	N110359	BEARING
Fig. 162	611737-01	LINK
Fig. 163	569624-01	BUTTON
Fig. 164	562097-13	SCREW
Fig. 800	286436-00	GREASE
Fig. 816	946194-00	BRAND LABEL
Fig. 821	396090-00	NP: DW821 T3
Fig. 856	DW4619	5X1/4 FASTCUT BK

mmToolParts
Big Time Experience. Small Town Service. .com