
# DW967K-CA Type 1 - Parts List

Use the figure number to match each part to the corresponding parts schematic.






mmToolParts
Big Time Experience. Small Town Service. .com

# DW967K-CA Type 1 - Parts List

Use the figure number to match each part to the corresponding parts schematic.

| | | |
|---|---|---|
| Fig. 1 | 392654-00 | CLAMSHELL SA |
| Fig. 2 | 151500-02 | MOTOR & PINION |
| Fig. 3 | 153032-00 | TRANSMISSION SA |
| Fig. 4 | 696631-00 | BALL |
| Fig. 5 | 389745-00 | SLEEVE |
| Fig. 6 | 151359-00 | SPRING |
| Fig. 7 | 152274-08 | SWITCH |
| Fig. 8 | 151296-00 | SLIDER |
| Fig. 9 | 151934-00 | SUPPORT. REAR |
| Fig. 10 | 151933-00 | SUPPORT. FRONT |
| Fig. 11 | 151489-02 | WHEEL |
| Fig. 12 | 152923-00 | POTENTIOMETER SA |
| Fig. 13 | 5140014-59 | RETAINER |
| Fig. 14 | 148354-03 | HOLDER |
| Fig. 15 | 607906-07 | PHILLIPS BIT |
| Fig. 16 | 330045-02 | SCREW |
| Fig. 17 | DW9061 | 9.6 HIGH CAP BATTRY |
| Fig. 18 | 330019-04 | SCREW |
| Fig. 19 | 046376-00 | PIN |
| Fig. 20 | 153033-00 | RING |
| Fig. 21 | 152466-00 | NAMEPLATE |
| Fig. 22 | 395657-00 | BRAND LABEL |
| Fig. 861 | 381121-00 | KITBOX |
| Fig. 867 | 645221-00 | CAP |
| Fig. 871 | DW9106 | 1 HR. FAST CHARGER |

mmToolParts
Big Time Experience. Small Town Service. .com