
DWE4010-B2 Type 1 - Parts List

Use the figure number to match each part to the corresponding parts schematic.



mmToolParts
Big Time Experience. Small Town Service. .com

DWE4010-B2 Type 1 - Parts List

Use the figure number to match each part to the corresponding parts schematic.

Fig. 101	401702-08	ARMATURE
Fig. 102	N336120	FIELD SA
Fig. 103	945614-01	SWITCH
Fig. 104	939539-01	BRUSH CUT OFF
Fig. 105	N344345	POWER CORD
Fig. 106	N134466	OUTER FLANGE
Fig. 107	391969-00	INNER FLANGE
Fig. 108	562160-06	SCREW
Fig. 109	N043269	RETAINING PLATE
Fig. 110	N042944	GUARD
Fig. 111	393576-00	RING
Fig. 112	330045-06	SCREW
Fig. 113	945298-01	GEARCASE COVER
Fig. 114	N318739	SPINDLE
Fig. 116	N918736	CORD PROTECTOR
Fig. 117	657177-00	GEAR
Fig. 118	562097-01	SCREW
Fig. 119	N358559	GEARCASE SA
Fig. 121	562211-00	HANDLE SIDE SA
Fig. 122	945299-00	FLANGE
Fig. 123	945292-00	NUT
Fig. 124	944575-00	BUTTON
Fig. 125	562210-00	SPRING
Fig. 126	944571-00	SPINDLE LOCK
Fig. 127	605040-22	BEARING
Fig. 128	641823-00	SLEEVE
Fig. 129	401623-00	BAFFLE
Fig. 130	949638-01	BUFFER
Fig. 132	606574-01SV	BRUSH HOLDER

mmToolParts
Big Time Experience. Small Town Service. .com

DWE4010-B2 Type 1 - Parts List

Use the figure number to match each part to the corresponding parts schematic.

Fig. 133	562204-00	SPRING
Fig. 134	609299-00	FIELDCASE
Fig. 135	605040-03	BEARING BALL
Fig. 136	394938-06	END CAP
Fig. 137	N312079	SWITCH SUPPORT
Fig. 138	401680-00	WRENCH
Fig. 139	562097-05	SCREW
Fig. 140	401622-01	FLANGE
Fig. 145	562097-00	SCREW
Fig. 149	641893-00	FELT SEAL
Fig. 153	657178-00	PINION
Fig. 160	N110359	BEARING
Fig. 162	611737-01	LINK
Fig. 163	569624-01	BUTTON
Fig. 164	562097-13	SCREW
Fig. 166	398906-00	SPACER INSULATING
Fig. 171	393799-00	O RING
Fig. 195	N107295	HEX KEY
Fig. 800	286436-00	GREASE
Fig. 800	30301914-01	GREASE
Fig. 816	946194-00	BRAND LABEL
Fig. 821	N355744	NAME PLATE

mmToolParts
Big Time Experience. Small Town Service. .com