
DWE4118-AR Type 1 - Parts List

Use the figure number to match each part to the corresponding parts schematic.



mmToolParts
Big Time Experience. Small Town Service. .com

DWE4118-AR Type 1 - Parts List

Use the figure number to match each part to the corresponding parts schematic.

Fig. 3	N516995	GUARD
Fig. 4	N516962	SCREW
Fig. 5	N525975	GUARD RET PLATE
Fig. 6	393576-00	RING
Fig. 7	N520080	SCREW
Fig. 8	N516728	GEARCASE
Fig. 10	641893-00	FELT SEAL
Fig. 11	NA156500	BEARING
Fig. 12	N520065	FLANGE
Fig. 16	N520085	SCREW
Fig. 17	N499495	SPINDLE LOCK
Fig. 18	N520072	SPRING
Fig. 19	N499496	BUTTON
Fig. 20	49205017	NUT
Fig. 21	661243-00	GEAR & PINION
Fig. 22	N110359	BEARING
Fig. 23	401622-01	FLANGE
Fig. 25	605040-03	BEARING BALL
Fig. 26	930275-00	SLEEVE
Fig. 27	N522613	BAFFLE
Fig. 28	N512593	HANDLE SIDE SA
Fig. 29	N615209	FIELD SA
Fig. 30	N327459	SWITCH
Fig. 31	N513692	SWITCH SUPPORT
Fig. 32	N520087	SCREW
Fig. 33	N506686	FIELDCASE
Fig. 34	641081-00	CORD PROTECTOR
Fig. 35	N517652	END CAP
Fig. 37	N519344	BUTTON

mmToolParts
Big Time Experience. Small Town Service. .com

DWE4118-AR Type 1 - Parts List

Use the figure number to match each part to the corresponding parts schematic.

Fig. 38	N566924	BRUSH HOLDER SA
Fig. 39	N520084	SCREW
Fig. 40	N035676	BRUSH PAIR 230V
Fig. 42	562204-00	SPRING
Fig. 43	N525990	CORD CLAMP
Fig. 44	N526221	SPRING
Fig. 45	N510166	LINK
Fig. 46	NA366089	MODULE
Fig. 47	N514046	MAGNET
Fig. 48	N527000	LABEL
Fig. 49	N107295	HEX KEY
Fig. 300	N561809	GEARCASE SA
Fig. 301	N615212	ARMATURE SA

mmToolParts
Big Time Experience. Small Town Service. .com