
# JET JTAS-10 | Stock 708510

## Diagram A - Table and Cabinet

Shared JET list: match 10/12-inch, horsepower, phase and serial-number variants




mmToolParts
Big Time Experience. Small Town Service. .com

# JET JTAS-10 | Stock 708510

## Parts List A - Table and Cabinet

Original JET part numbers | Shared 10-inch / 12-inch assembly list

| Ref. | Part number | Description | Size / specification | Qty. |
|---|---|---|---|---|
| 1 | JTAS10-1 | Lock Knob | | 1 |
| 2 | JTAS10-2 | Miter Gauge Body | | 1 |
| 3 | TS-1540031 | Hex Nut | M5 | 3 |
| 4 | JTAS10-4 | Pointer | | 1 |
| 5 | JTAS10-5 | Stop Link | | 1 |
| 6 | TS-1521011 | Set Screw | M4x4 | 1 |
| 7 | JTAS10-7 | Special Pin | M3x6 | 1 |
| 8 | JTAS10-8 | Screw | M5x20 | 1 |
| 9 | JTAS10-9 | Guide Bar | | 1 |
| 10 | JTAS10-10 | Guide Washer | | 1 |
| 11 | JTAS10-11 | Flat Head Screw | M6x8 | 1 |
| | JTAS10-MG | Miter Gauge Assembly (#1-11) | | 1 |
| 12 | TS-0267041 | Set Screw | 1/4x3/8 | 4 |
| 13 | JTAS10-13 | Table Insert | | 1 |
| | JTAS12-13 | Table Insert | | 1 |
| 14 | JTAS10-14W | Table | | 1 |
| | JTAS12-14W | Table | | 1 |
| 15 | JTAS10-15W | Extension Wing | | 2 |
| | JTAS12-15W | Extension Wing | | 2 |
| 18 | TS-0061051 | Hex Socket Cap Screw | 7/16x1-1/2 | 6 |
| 19 | TS-0720101 | Lock Washer | 7/16 | 6 |
| 20 | TS-0680051 | Flat Washer | | 6 |
| 21 | TS-0720081 | Lock Washer | 5/16 | 1 |
| 22 | JTAS10-22W | Switch Plate | | 1 |
| 23 | JTAS10-23 | Magnetic Switch | 3HP, 1Ph, 230V | 1 |
| | JTAS10-23A | Magnetic Switch | 5HP, 3Ph, 230V | 1 |
| | JTAS10-23B | Magnetic Switch | 5HP, 3Ph, 460V | 1 |
| | JTAS12-23 | Magnetic Switch * | 5HP, 1Ph, 230V | 1 |

Shared JTAS-10/12 list: match the saw size, horsepower and phase. * 10-inch saws with a 5 HP, 1Ph motor use these parts. ** Switch Brace Kit contains bracket, screw, nut, star washer and 8mm hex wrench. Blank references and sizes are retained from JET.

mmToolParts
Big Time Experience. Small Town Service. .com

# JET JTAS-10 | Stock 708510

## Parts List A - Table and Cabinet (continued)

Original JET part numbers | Shared 10-inch / 12-inch assembly list

| Ref. | Part number | Description | Size / specification | Qty. |
|---|---|---|---|---|
| 24 | JTAS10-24 | Screw | 3/16x3/4 | 2 |
| 26 | JTAS10-26 | Cord Connector | | 2 |
| 27 | JTAS10-27 | Cord Clamp | | 3 |
| | JTAS12-27 | Cord Clamp | | 3 |
| 28 | JTAS10-28 | Tap Screw | M5x10 | 12 |
| 29 | JTAS10-29 | Cord Plate | | 1 |
| | JTAS12-29 | Cord Plate * | | 1 |
| 30 | JTAS10-30 | Identification Plate | | 1 |
| | JTAS12-30 | Identification Plate | | 1 |
| 31 | JTAS10-31 | Power Cord (switch to motor) | | 1 |
| | JTAS12-31 | Power Cord (switch to motor) * | | 1 |
| 32 | JTAS10-32 | Power Cord | | 1 |
| | JTAS12-32 | Power Cord * | | 1 |
| 33 | JTAS10-33 | Power Cord Sleeve | | 1 |
| | JTAS12-33 | Power Cord Sleeve * | | 1 |
| 34 | JTAS10-34 | Tilt Scale | | 1 |
| 35 | JTAS10-35 | Warning Label | | 1 |
| 36 | JTAS10-36 | JET Plaque | | 1 |
| 37 | JTAS10-37 | Flat Head Screw | 3/16x3/8 | 2 |
| 38 | JTAS10-38W | Cabinet | | 1 |
| | JTAS12-38W | Cabinet | | 1 |
| 39 | TS-1482101 | Hex Cap Bolt | M6x50 | 1 |
| 40 | TS-0680021 | Flat Washer | 1/4 | 2 |
| 41 | JTAS10-41 | Spring | | 1 |
| 42 | JTAS10-42 | Foam Strip | | 1 |
| 43 | JTAS10-43W | Motor Cover | | 1 |
| | JTAS12-43W | Motor Cover | | 1 |
| 44 | TS-1540021 | Hex Nut | M6 | 1 |

Shared JTAS-10/12 list: match the saw size, horsepower and phase. * 10-inch saws with a 5 HP, 1Ph motor use these parts. ** Switch Brace Kit contains bracket, screw, nut, star washer and 8mm hex wrench. Blank references and sizes are retained from JET.

mmToolParts
Big Time Experience. Small Town Service. .com

# JET JTAS-10 | Stock 708510

## Parts List A - Table and Cabinet (continued)

Original JET part numbers | Shared 10-inch / 12-inch assembly list

| Ref. | Part number | Description | Size / specification | Qty. |
|---|---|---|---|---|
| 45 | JTAS10-45 | Handle | | 1 |
| 46 | JTAS10-47 | Cord Clamp Plate | | 1 |
| | JTAS12-47 | Cord Clamp Plate * | | 1 |
| 47 | TS-0210011 | Hex Socket Cap Screw | 7/16x3/4 | 4 |
| 48 | TS-0680011 | Flat Washer | 3/16 | 4 |
| 49 | JTAS10-50W | Lower Panel | | 1 |
| | JTAS12-50W | Lower Panel | | 1 |
| 50 | JTAS10-51W | Dust Hose Adapter | | 1 |
| 51 | JTAS10-52W | Switch Brace Kit ** | | 1 |
| | JTAS12-52W | Switch Brace Kit ** | | 1 |
| 52 | JTAS10-53 | Screw | 3/16x1 | 1 |
| 53 | JTAS10-54 | Nut | 3/16 | 3 |
| 54 | JTAS10-55 | Star Washer | 3/16 | 1 |


Shared JTAS-10/12 list: match the saw size, horsepower and phase. * 10-inch saws with a 5 HP, 1Ph motor use these parts. ** Switch Brace Kit contains bracket, screw, nut, star washer and 8mm hex wrench. Blank references and sizes are retained from JET.

mmToolParts
Big Time Experience. Small Town Service. .com

# JET JTAS-10 | Stock 708510

## Diagram B - Blade Guard

Shared JET list: match 10/12-inch, horsepower, phase and serial-number variants




mmToolParts
Big Time Experience. Small Town Service. .com

# JET JTAS-10 | Stock 708510

## Parts List B - Blade Guard

Original JET part numbers | Shared 10-inch / 12-inch assembly list

| Ref. | Part number | Description | Size / specification | Qty. |
|---|---|---|---|---|
| | JTAS10-BG | Blade Guard Assembly (#1-10/13/23-26) | | 1 |
| | JTAS12-BG | Blade Guard Assembly (#1-10/13/23-26) | | 1 |
| 1 | JTAS10-G1 | Pin | | 1 |
| 2 | JTAS10-G2 | Guard | | 1 |
| | JTAS12-G2 | Guard | | 1 |
| 3 | TS-0207091 | Hex Socket Cap Screw | 1/4x1-1/2 | 1 |
| 4 | TS-0680021 | Flat Washer | 1/4 | 1 |
| 5 | JTAS10-G5 | Spacer | | 2 |
| 6 | TS-0561011 | Hex Nut | 1/4 | 1 |
| 7 | JTAS10-G7 | Lock Grommet | | 3 |
| 8 | JTAS10-G8 | Warning Label | | 1 |
| 9 | JTAS10-G9 | Support Arm | | 1 |
| | JTAS12-G9 | Support Arm | | 1 |
| 10 | JTAS10-G10 | Pin | | 1 |
| 11 | TS-0208061 | Hex Cap Bolt | 5/16x1 | 2 |
| 12 | JTAS10-G12 | Plate | | 1 |
| 13 | JTAS10-G13 | Splitter | | 1 |
| | JTAS12-G13 | Splitter | | 1 |
| 14 | TS-0051071 | Hex Cap Bolt | 5/16x1-1/2 | 2 |
| 15 | TS-0680031 | Flat Washer | 5/16 | 6 |
| 16 | JTAS10-G15 | Upper Blade Guard Bracket | | 1 |
| 17 | JTAS10-G16 | Lower Blade Guard Bracket | | 1 |
| 18 | TS-0720081 | Lock Washer | 5/16 | 5 |
| 19 | TS-0561021 | Hex Nut | 5/16 | 2 |
| 20 | TS-0270031 | Set Screw | 5/16x3/8 | 2 |
| 21 | JTAS10-G21 | Shaft (serial #507050 and below) | | 1 |
| | JTAS10-G21A | Shaft (serial #508051 and above) | | 1 |
| 22 | TS-0720141 | Lock Washer | 5/8 | 1 |

Shared JTAS-10/12 list: match the saw size and serial number. Shaft serial ranges are reproduced exactly as printed: 507050 and below / 508051 and above. Unnumbered assemblies and not-shown parts are retained.

mmToolParts
Big Time Experience. Small Town Service. .com

# JET JTAS-10 | Stock 708510

## Parts List B - Blade Guard (continued)

Original JET part numbers | Shared 10-inch / 12-inch assembly list

| Ref. | Part number | Description | Size / specification | Qty. |
|---|---|---|---|---|
| 23 | JTAS10-G23 | Pin | | 1 |
| 24 | JTAS10-G24 | Anti-Kickback Pawl | | 2 |
| | JTAS12-G24 | Anti-Kickback Pawl | | 2 |
| 25 | JTAS10-G25 | Spring | | 1 |
| 26 | JTAS10-G26 | Spacer | | 2 |
| 27 | TS-0680031 | Flat Washer | 5/16 | 1 |
| 28 | TS-0051021 | Hex Cap Bolt | 5/16x5/8 | 1 |
| 29 | JTAS10-G29 | Bracket | | 1 |
| 30 | TS-0208021 | Hex Socket Cap Screw | 5/16x1/2 | 2 |
| | TS-0561071 | Hex Nut - 5/8 (serial #507050 and below - not shown) | | 1 |
| | 477446 | 12mm Combination Wrench (not shown) | | 1 |


Shared JTAS-10/12 list: match the saw size and serial number. Shaft serial ranges are reproduced exactly as printed: 507050 and below / 508051 and above. Unnumbered assemblies and not-shown parts are retained.

mmToolParts
Big Time Experience. Small Town Service. .com

# JET JTAS-10 | Stock 708510

## Diagram C - Motor and Trunnion

Shared JET list: match 10/12-inch, horsepower, phase and serial-number variants




mmToolParts
Big Time Experience. Small Town Service. .com

# JET JTAS-10 | Stock 708510

## Parts List C - Motor and Trunnion

Original JET part numbers | Shared 10-inch / 12-inch assembly list

| Ref. | Part number | Description | Size / specification | Qty. |
|---|---|---|---|---|
| 101 | JTAS10-101 | Arbor Nut | | 1 |
| | JTAS12-101 | Arbor Nut | | 1 |
| 102 | JTAS10-102 | Arbor Flange | | 1 |
| | JTAS12-102 | Arbor Flange | | 1 |
| 104 | JTAS10-104 | Arbor with Flange | | 1 |
| | JTAS12-104 | Arbor with Flange | | 1 |
| 105 | JTAS10-105 | Key | M5x1-1/2 | 1 |
| | JTAS12-105 | Key | | 1 |
| 106 | BB-6203ZZ | Ball Bearing (JTAS-10 only) | | 2 |
| | BB-6005ZZ | Ball Bearing (JTAS-12 only) | | 2 |
| 107 | JTAS10-107 | Bearing Load Spring | | 2 |
| 108 | JTAS10-108 | Bearing Load Spacer | | 2 |
| | JTAS12-108 | Bearing Load Spacer | | 2 |
| 109 | TS-0267041 | Set Screw | 1/4x3/8 | 6 |
| 110 | JTAS10-110 | Arbor Pulley | | 1 |
| | JTAS12-110 | Arbor Pulley | | 1 |
| 111 | TS-0209031 | Hex Socket Cap Screw | | 1 |
| 112 | JTAS10-112 | Key | 1/4x50 | 1 |
| 113 | TS-0720091 | Lock Washer | 3/8 | 10 |
| 114 | JTAS10-114 | Arbor Bracket | | 1 |
| | JTAS12-114 | Arbor Bracket | | 1 |
| 115 | JTAS10-115 | Spanner Nut | | 1 |
| | JTAS12-115 | Spanner Nut | | 1 |
| 116 | JTAS10-116 | Arbor Nut (JTAS-10 only) | 5/8 | 1 |
| | TS-0561081 | Hex Nut (JTAS-12 only) | 3/4 | 1 |
| 117 | JTAS10-117 | Spring Pin | M6x50 | 1 |
| 118 | JTAS10-118 | Key | 1/4x75 | 1 |
| 119 | TS-0680051 | Flat Washer | 7/16 | 2 |

Shared JTAS-10/12 list: match the saw size, horsepower and phase. Blank references and sizes are retained from JET. Reference 155 quantity: one for 12-inch saws; two for 10-inch saws.

mmToolParts
Big Time Experience. Small Town Service. .com

# JET JTAS-10 | Stock 708510

## Parts List C - Motor and Trunnion (continued)

Original JET part numbers | Shared 10-inch / 12-inch assembly list

| Ref. | Part number | Description | Size / specification | Qty. |
|---|---|---|---|---|
| 120 | TS-0091031 | Hex Cap Bolt | 7/16x1 | 2 |
| 121 | JTAS10-121 | Shaft | | 1 |
| 122 | JTAS10-122 | Motor Bracket | | 1 |
| 123 | JTAS10-123 | Pin | | 1 |
| 124 | JTAS10-124 | Spring Clip | | 2 |
| 125 | VB-A23 | V-Belt | | 3 |
| 126 | JTAS10-126 | Motor Plate | | 1 |
| 127 | JTAS10-127 | Motor Pulley | | 1 |
| 128 | TS-0680031 | Flat Washer | 5/16 | 4 |
| 129 | TS-0720081 | Lock Washer | 5/16 | 4 |
| 130 | TS-0051031 | Hex Cap Bolt | 5/16x3/4 | 4 |
| 131 | JTAS10-131 | Motor (3HP, 1Ph, 230V only) | | 1 |
| | JTAS10-131A | Motor (5HP, 3Ph, 230/460V) | | 1 |
| | JTAS12-131 | Motor (5HP, 1Ph, 230V only) | | 1 |
| 132 | TS-0209071 | Hex Socket Cap Screw | 3/8x1-1/2 | 5 |
| 133 | JTAS10-133 | Rear Trunnion Bracket | | 1 |
| 134 | TS-0561031 | Hex Nut | 3/8 | 5 |
| 135 | TS-0209051 | Hex Socket Cap Screw | 3/8x1 | 5 |
| 136 | JTAS10-136 | Spring Pin | M8x25 | 4 |
| 137 | TS-0561081 | Hex Nut | 3/4 | 4 |
| 138 | JTAS10-138 | Fiber Washer | | 4 |
| 139 | JTAS10-139 | Rear Trunnion | | 1 |
| 140 | JTAS10-140 | Bushing | | 2 |
| 141 | JTAS10-141 | Yoke | | 1 |
| | JTAS12-141 | Yoke | | 1 |
| 142 | TS-0270011 | Set Screw | 5/16x1/4 | 4 |
| 143 | JTAS10-143 | Collar | | 2 |
| 144 | JTAS10-144 | Shaft | | 1 |

Shared JTAS-10/12 list: match the saw size, horsepower and phase. Blank references and sizes are retained from JET. Reference 155 quantity: one for 12-inch saws; two for 10-inch saws.

mmToolParts
Big Time Experience. Small Town Service. .com

# JET JTAS-10 | Stock 708510

## Parts List C - Motor and Trunnion (continued)

Original JET part numbers | Shared 10-inch / 12-inch assembly list

| Ref. | Part number | Description | Size / specification | Qty. |
|---|---|---|---|---|
| | JTAS12-144 | Shaft | | 1 |
| 145 | JTAS10-145 | Spring Pin | M5x30 | 2 |
| 146 | JTAS10-146 | Worm Gear | | 2 |
| 147 | JTAS10-147 | Lock Pin | | 4 |
| 148 | JTAS10-148 | Key | M5x35 | 2 |
| 149 | TS-0051071 | Hex Cap Bolt (JTAS-10 only) | 5/16x1-1/2 | 2 |
| | JTAS12-149 | Hex Cap Bolt (JTAS-12 only) | | 2 |
| 150 | JTAS10-150 | Dust Deflector | | 1 |
| | JTAS12-150 | Dust Deflector | | 1 |
| 151 | JTAS10-151 | Spacer (JTAS-10 only) | | 2 |
| 152 | JTAS10-152 | Front Trunnion | | 1 |
| | JTAS10-TA | Trunnion Assy. (#113, 135-141) | | 1 |
| 153 | TS-0051021 | Hex Cap Bolt | 5/16x5/8 | 2 |
| 154 | TS-0561021 | Hex Nut | 5/16 | 2 |
| 155 | JTAS10-155 | Lock Knob | | 1 (12-inch) / 2 (10-inch) |
| 155-1 | JTAS12-155 | Lock Knob (JTAS-12 only) | | 1 |
| 156 | JTAS10-156 | Fiber Washer | | 2 |
| 157 | TS-0208061 | Hex Socket Cap Screw (JTAS-10 only) | 5/16x1 | 2 |
| | TS-0208101 | Hex Socket Cap Screw (JTAS-12 only) | 5/16x2 | 2 |
| 158 | JTAS10-158 | Front Trunnion Bracket | | 1 |
| | JTAS12-158 | Front Trunnion Bracket | | 1 |
| 159 | JTAS10-159 | Hand Wheel Handle | | 2 |
| 160 | JTAS10-160 | Handle | | 2 |
| 161 | JTAS10-161 | Shield Plate | | 1 |
| 161-1 | JTAS12-161 | Adapter (JTAS-12 only) | | 1 |
| 162 | JTAS10-162 | Round Head Screw | 1/4x3/8 | 1 |
| 163 | JTAS10-163 | Pointer | 3/8 | 1 |

Shared JTAS-10/12 list: match the saw size, horsepower and phase. Blank references and sizes are retained from JET. Reference 155 quantity: one for 12-inch saws; two for 10-inch saws.

mmToolParts
Big Time Experience. Small Town Service. .com

# JET JTAS-10 | Stock 708510

## Parts List C - Motor and Trunnion (continued)

Original JET part numbers | Shared 10-inch / 12-inch assembly list

| Ref. | Part number | Description | Size / specification | Qty. |
|---|---|---|---|---|
| 164 | JTAS10-164 | Pointer Bracket | | 1 |
| 165 | JTAS10-165 | Round Head Screw | 3/16x2 | 2 |
| 166 | JTAS10-166 | Guide Block | | 1 |
| 167 | TS-0680041 | Flat Washer | 3/8 | 1 |
| 168 | TS-0060071 | Hex Cap Bolt | 3/8x1-1/2 | 1 |
| 169 | JTAS10-169 | Tilt Shaft | | 1 |
| | JTAS12-169 | Tilt Shaft | | 1 |
| 170 | JTAS10-170 | Wrench | | 1 |
| | JTAS12-170 | Wrench | | 1 |

Shared JTAS-10/12 list: match the saw size, horsepower and phase. Blank references and sizes are retained from JET. Reference 155 quantity: one for 12-inch saws; two for 10-inch saws.

mmToolParts
Big Time Experience. Small Town Service. .com